

Release Note for Vigor2110 Series

Firmware Version: 3.3.0

Date: April, 10, 2009

Applied Models:

Vigor2110, Vigor2110n, Vigor2110Vn

Please ensure you download and use the latest router tools when upgrading the firmware.

New Features

- Support Hardware Protocol Acceleration.
- Support various Ring Pattern types for FXS port.
- Support "Loop Through To PSTN" message on VoIP Status page.
- Support QoS telnet command.
- Support "Select All" button in IM object page, P2P object page, Protocol object page and Misc Object page.
- Support a telnet command to receive illegal ARP REPLY packet (Ethernet source address doesn't match ARP sender address).
- Support "Traffic Graph" on Diagnostics page.
- Support SIP account on user mode operation.
- Display data in "green" when encrypted in VOIP Status page.

Improvement

- Improved: the stability for VoIP
- Improved: the problem of nmap scan
- Improved: problem happened to SIP client registration. SIP ALG handle specific case; where the SIP proxy server is located in the LAN side; SIP Phone is located in the WAN side.
- Corrected: IM-P2P mail alert not work
- Corrected: VPN routing can not be removed in special case
- Corrected: BytesSent & BytesReceived of TR069 display wrong values
- Corrected: login fail on WUI sometimes
- Corrected: crash problem for ProvisionKeepParameter of TR069
- Corrected: WUI firmware upgrade fails when the browser is Firefox 3.x.x
- Corrected: CPA query timeout while DMZ host enabled

- Corrected: WAN1 MAC is wrong after MAC address is set manually
- Corrected: PPTP WAN cannot dial out due to sending GRE encapsulated TCP packet to server
- Corrected: display problem of WCF and CSM LED
- Corrected: only one phone can loop through to PSTN when software relay and hardware relay loop through to PSTN
- Corrected: WAN IP Alias page cannot be cleared
- Corrected: display problem of IP ping telnet command
- Corrected: “phase1 mode” and “phase 1 proposal” can't be saved properly in IKE advanced settings page
- Change "VPN Connection Through" into "VPN Dial-Out Through"

Known Issue

- None

Notes

Modifications

- None