

Release Note for Vigor2132 Series

Firmware Version: 3.7.8

Release Date: May 14, 2015

**Applied Models:
Vigor2132FVn, Vigor2132Vac**

New Features

- Support Route Policy V4 and virtual WAN interface.
- Support RFC3021.
- Support wireless LAN 11ac.

Improvement

- Corrected: Error occurred in session control.
- Corrected: Web user interface of Vigor router cannot be logged into via IPv6 TSPC connection.
- Corrected: The function of disabling Auto logout failed in user mode.
- Corrected: Web user interface error when IPv6 was turned off.
- Corrected: CSM LED did not light on after configured firewall default rule settings.
- Corrected: Number error occurred in Wireless LAN>>Station List.
- Corrected: Reboot error occurred while performing route policy loop detection.
- Corrected: Display error of WAN physical type (missed 1G setting).
- Corrected: 802.1X failed to get IP.
- Corrected: Telnet command error of using '*wl acl clear*'.
- Corrected: Unable to access into to LAN DNS setting page under GUI Map.
- Improved: Add setting descriptions for telnet command '*wl wlanconfig*'.
- Improved: Add IPv6 TSPC status option on Diagnostics.
- Improved: Wi-Fi ACL (access control) can set up identical MAC addresses.

Known Issue

- None

Notes

- Please use the latest boot-loader, or need to upgrade 3752_B1 (ask your dealer) first, otherwise, it will encounter firmware upload issue.