

Release Note for Vigor2820 Series

Firmware Version: 3.3.2.1

Built Date: July 29, 2009

**Applied Models: Vigor2820/
Vigor2820V/Vigor2820n/Vigor2820Vn/
Vigor2820VS/Vigor2820VSn**

- File and Modem Code

(1)For Annex A Model,

- "v2820_v0332_211011_A" is used for modem code 211011(Standard).
- "v2820_v0332_211801_A" is used for modem code 211801.
- "v2820_v0332_2121501_A" is used for modem code 2121501.
- "v2820_v0332_2211201_A" is used for modem code 2211201.
- "v2820_v0332_232201_A" is used for modem code 232201.

(2)For Annex B Model,

- "v2820_v0332_2111112_B" is used for modem code 2111112. (Standard)
- "v2820_v0332_214702_B" is used for modem code 214702.
- "v2820_v0332_215202_B" is used for modem code 215202.
- "v2820_v0332_2121302_B" is used for modem code 2121302.
- "v2820_v0332_2111312_B" is used for modem code 2111312.
- "v2820_v0332_2111302_B" is used for modem code 2111302.

New Features

- None

Improvement

- Wireless SSID default name has been changed to "DrayTek".
- Improved: Router stability is not good after VPN IPSec service is disabled.

Known Issue

- ZFone 0.92 build 218 will pop up two identical windows that say "unsupported type of error was received" when SAS is generated. However, the voice protection afterward and

SAS are all good. Above scenario only happens if vigor calls zfone for the very first time!!
Vigor to Vigor call doesn't have this issue!!

Notes

Modifications

- None