

Release Note for Vigor2820 Series

Firmware Version: 3.3.5.2

Built Date: April 21, 2011

Applied Models:

**Vigor2820/2820V/Vigor2820n/Vigor2820Vn/Vigor2820VS/
Vigor2820VSn**

- File and Modem Code

(1)For Annex A Model,

- "v2820_v3352_211011_A" is used for modem code 211011(Standard).
- "v2820_v3352_232201_A." is used for modem code 232201 (recommended for UK-SEG only).
- "v2820_v3352_211801_A" is used for modem code 211801.
- "v2820_v3352_2121501_A" is used for modem code 2121501.
- "v2820_v3352_2211201_A" is used for modem code 2211201.
- "v2830_v3352_243601_A" is used for modem code 243601.
- "v2830_v3352_243701_A" is used for modem code 243701.
- "v2830_v3352_2431301_A" is used for modem code 2431301.
- "v2830_v3352_244001_A" is used for modem code 244001.
- "v2830_v3352_2471201_A" is used for modem code 2471201 .

(2)For Annex B Model,

- "v2820_v3352_2111112_B" is used for modem code 2111112. (Standard)
- "v2830_v3352_2121302_B" is used for modem code 2121302.(recommended for Slovakia only)
- "v2820_v3352_2111302_B" is used for modem code 2111302 (recommended for Czech only).
- "v2820_v3352_214702_B" is used for modem code 214702.
- "v2820_v3352_215202_B" is used for modem code 215202.
- "v2820_v3352_2121302_B" is used for modem code 2121302.
- "v2820_v3352_2111312_B" is used for modem code 2111312.

New Features

- SMTP port can be modified by the user.

- Support TR-069 parameters for matching with VigorACS SI.
- Support APP QoS for Firewall.

Improvement

For VPN

- Corrected: IPSec remote dial-in can be connected even no IPSec profile is enabled.
- Corrected: Access list blocks the accessing into web configurator of the router through remote VPN.

For NAT

- Corrected: NAT loopback problem.

For VoIP

- Improved: VoIP stability problem.
- Improved: Online Status for VoIP.
- Improved: Fax relay cannot receive all of the data from the caller.
- Improved: Add a new telnet command to disable/enable VoIP service.

For ISDN

- Corrected: One way talk issue for "call pickup" scenario with VigorIPPBX router.
- Corrected: The first character is missing by the incoming call.
- Corrected: When ISDN2-S0 phone is used to dial "call pick up" number, the router will reboot.

For Others

- Corrected: Rename **Port Trigger** with **Port Triggering**.

Related Information

- Get the document, please visit <http://www.draytek.com/user/PdInfoDetail.php?Id=72#PdQuLinkInfo>
- Get the new firmware, please visit <http://www.draytek.com/user/SupportDownloads.php>
- Get the customer service support, please visit <http://www.draytek.com/user/ContactHeadquarters.php#Headquarters>
- Get the regulatory compliance information <http://www.draytek.com/user/AboutRegulatory.php>
- Get information for global partners <http://www.draytek.com/user/Globalpartners.php>

Known Issue

- None

Notes

Modifications

- None