

Release Note for Vigor3900 Series

Firmware Version: 1.0.8.2
Release Date: June 23, 2014
Applied Model: Vigor3900

New Features

- None.

Improvement

- Improved: PPTP connection stability.
- Improved: Web Portal stability.
- Improved: Remove management port setting which may occupy port redirection.
- Improved: Improve the stability of High Availability function.
- Improved: Add telnet timeout if not login in 60 seconds.
- Fixed: CPU usage is too high when data flow monitor is enabled.
- Fixed: The function of SSL VPN client can't work.
- Fixed: A problem of WCF license occurred when HA is enabled.
- Fixed: CVM can't perform configuration backup.
- Fixed: NAT Loopback to LAN More Subnet doesn't work.
- Fixed: DNS for PPTP Remote dial-in is not assigned according to the LAN Profile.
- Fixed: Reboot with Customized Configurations bug.
- Fixed: When firewall default policy (block) is used, HTTP is still available for access.
- Fixed: Web portal still supports URL redirect when login mode is disabled.
- Fixed: Packet count error when PPTP acceleration is enabled.
- Fixed: mOTP User profile cannot be saved without Password.
- Fixed: WAN Priority Bits doesn't work.
- Fixed: An error occurred in time object.
- Fixed: An error occurred in WAN >> Switch mode >> double tag.
- Improved: Upgrade OpenSSL to 0.9.8za for some security issues.
- Fixed: WCF (Web Content Filter) cannot be enabled when myVigor Portal changes Service Name from Commtouch to Cyren.
- Fixed: Some bugs about HA (High Availability).
- Fixed: DDNS failover 3G WAN didn't work.
- Fixed: Daylight Saving didn't work for UTC+1(Ljubljana).

Known Issue

- VPN Trunk tunnel doesn't work well when the profile name is more than 15 characters.
- You need to disable "Force IPsec with L2TP" options for pure L2TP tunnel in **VPN and Remote Access >> PPP General Setup**.

Notes

Modifications

- None