

# Release Note for Vigor3900 Series

**Firmware Version: 1.1.0.1**  
**Release Date: August 31, 2015**  
**Applied Model: Vigor3900**

Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.8.x and later.

## New Features

- None.

## Improvement

- Fixed: Port Redirection didn't work for specific configuration.
- Fixed: Syslog stopped writing to USB disk after reboot.
- Fixed: Unable to modify Telnet login Max-Failed Times in Fail to Ban.
- Fixed: Unable to display Netbios Name in ARP Cache Table.
- Fixed: Issues of certification generation and uploading.
- Improved: WAN failed over time.
- Improved: Support 4G Dongle Huawei E3372.
- Improved: Support DHCP option 15 (DNS suffix) for remote dial in VPN client.
- Improved: Upgrade OpenSSL to 0.9.8zg for vulnerabilities.

## Known Issue

- VPN Trunk tunnel doesn't work well when the profile name is more than 15 characters.
- You need to disable "Force IPsec with L2TP" options for pure L2TP tunnel in VPN and Remote Access >> PPP General Setup.

## Notes

### ***Modifications***

None