

Release Note for Vigor3900 Series

Firmware Version: 1.2.2
Release Date: October 26, 2016
Applied Model:
Vigor3900

Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.8.x and later.

New Features

- None.

Improvement

- Improved: Improve the high memory usage issue after running for long period of time.
- Corrected: FTP active mode wasn't passed correctly.
- Corrected: Packet Monitor 'Host' option didn't work.
- Corrected: MOTP user profile could not be saved without Password.
- Corrected: Wrong TTL value appeared in Session Table.
- Corrected: SSL VPN was unstable with MacOS SmartVPN client.

Known Issue

- VPN Trunk tunnel doesn't work well when the profile name is more than 15 characters.
- You need to disable "Force IPsec with L2TP" options for pure L2TP tunnel in VPN and Remote Access >> PPP General Setup.

Notes

Modifications

None