

Release Note for Vigor3910 Series

Firmware Version:	3.9.2.2
Release Type:	Normal
Applied Models:	Vigor3910

New Features

- None.

Improvement

- Corrected: An issue of router reboot, when a big DHCP packet was received.
- Corrected: An socket run out issue when TR069 and STUN requests DNS failed.
- Corrected: An issue that some IPsec VPN tunnels could not pass traffics when there were many IPsec VPN connections.
- Corrected: An issue that Windows IKEv2 EAP Client by Static IP assignment failed to access the VPN network after IPsec rekey.
- Corrected: An issue that CPU usage in Dashboard was lower than the real CPU usage after some time.
- Improved: Add a sort function to display VPN Connection Status (VPN and Remote Access>>Connection Management).

Known Issue

- Once upgraded to 3.9.2.2, configuring route policy settings and then get downgraded to 3.9.2.1 or older, route policy “to” and “failover” to settings are likely to be wrong. Always backup your config before firmware up(down)grading.
- Once upgraded to 3.9.2.1, configure IP Bind MAC settings and then get downgraded to 3.9.1 again. The IP Bind MAC settings will disappear. So make sure the IP Bind MAC settings is backed up before downgrading.

Note

The following items will be ready in the future release:

- USB Applications
- WAN >> Multi-VLAN >> Port-based bridge

The following traffic will be accelerated (in the fast path) in the future release:

- All IPv6 traffic