

Release Note for VigorIPPBX 3510 Series

Firmware Version: 3.5.8
Release Date: August 13, 2013
Applied Models: VigorIPPBX™

The VigorIPPBX 3510 is a dual-WAN broadband router with IP PBX function. The 2nd WAN interface is shared with the 4th LAN port. These two WANs can connect to DSL/Cable modem or fiber media converter for policy-based load-balance, fail-over and BoD (Bandwidth on Demand); it also features advanced bandwidth control mechanism such as IP-layer QoS, NAT Session Limitation, Bandwidth Borrowed, etc., to allow easy, flexible, reliable access control and bandwidth management.

New Features

- Support RFC3326 for resolve hunt-group missed call display issue

Improvement

- Corrected: SSH access causes router reboot.
- Corrected: Turning on call forward (*72) may store wrong number.
- Corrected: A typo on call forward telnet command.
- Corrected: "Block unknown domain" causes calls from DDNS proxy can't work.

Known Issue

- SIP trunk and extension configuration backup are not compatible with IE6.0. Please use Firefox to test the feature.
- If ISDN trunk has existed incoming call and outgoing call at the same time, out-going call would not be disconnected when time budget exceeded until incoming call disconnected.

Notes

- Please use the firmware upgrade utility to backup/restore *V3510_xxx.cfg* and *VoipModule config*.
- As for the relation between VigorIPPBX router and System Prompt file, refer to **FAQ**:

Please upload the newest System Prompt after upgrading Vigor IPPBX firmware V3.5.6
for detailed information.

- To send a fax via IPPBX virtual fax function, you need to use Virtual FAX Utility.