Release Note for VigorConnect

Software Version:	1.8.2
Release Type:	Normal - Upgrade recommended when convenient
Applied System:	Windows 7, 8, 10, 11 / Linux / Raspberry Pi / Docker
Applied Models:	VigorAP 1000C, 1060C, 802, 810, 903, 906, 912C, 918R Series, 920R Series, 960C VigorSwitch P2500/G2500, P2280/G2280, P2280x/G2280x, P2100/G2100, P2121/G2121, P1280/G1280, P1085/G1085, G1080, P1092, FX2120, PQ2200xb/Q2200x, P1282/G1282, and Q2121x/PQ2121x.

VigorConnect is a software which provides centralized AP management and switch management for TR-069 based devices. VigorConnect has device status, monitor status of devices, or perform scheduling tasks such as firmware upgrade, configuration backup/restore and parameter profile for mass deployment of the managed devices.

New Features

- None.

Improvement

- Corrected: An issue with failure to disable the function of WUI HTTPS.
- Corrected: An issue with failure to upgrade the firmware for some Vigor switches (e.g., VigorSwitch P1282, G1282 and etc.) via Maintenance>>Firmware Upgrade.
- Corrected: An issue with the inconsistency of the total client number between Active Clients and the Device Overview, on the Dashboard.

Known Issue

- An issue that viewing Flow with FireFox (HTTPS) would block illegal HTTPS certificate issued by Grafana.