

Release Note for Vigor2830 Series

| | |
|-------------------|----------------------------------|
| Firmware Version: | 3.8.8.2 |
| Release Type: | Critical |
| Applied Models: | Vigor2830/Vigor2830n/Vigor2830Vn |

This is a critical update - You should upgrade such Vigor router immediately with firmware containing these improvements.

Vigor2830 series is an ADSL2+ router. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The gigabit WAN2 and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe.

In addition, Vigor2830 series supports USB interface for connecting USB printer to share printer or USB storage device for sharing files. Vigor2830 series provides two-level management to simplify the configuration of network connection. The user operation allows user accessing into WEB interface via simple configuration. However, if users want to have advanced configurations, they can access into WEB interface through administration operation.

New Features

- None.

Improvement

- This firmware includes improvements to harden the web interface against attacks. We have become aware of specific attacks against router, including DrayTek models where hackers have altered specific settings relating to your DNS servers and DHCP settings. You should urgently check those settings on your router. If they appear to have been tampered with, correct them and change your admin password and for any other config anomalies. Restore a config backup if you have one (from prior to the attack). We continue to investigate this issue but the first priority was to issue updated firmware.

Known Issue

- None.

File and Modem Code

(1)For Annex A Model,

- "v2830sb_a_3882" is used for modem code 211011(Standard).
- "v2830sb_a1_3882" is used for modem code 211801.
- "v2830sb_a2_3882" is used for modem code 2121501.
- "v2830sb_a3_3882" is used for modem code 2211201.
- "v2830sb_a4_3882" is used for modem code 232201 (recommended for UK-SEG)
- "v2830sb_a5_3882" is used for modem code 243601.
- "v2830sb_a6_3882" is used for modem code 2438821.
- "v2830sb_a7_3882" is used for modem code 2431301.
- "v2830sb_a8_3882" is used for modem code 244001.
- "v2830sb_a9_3882" is used for modem code 2471201.

(2)For Annex B Model,

- "v2830sb_b_3882" is used for modem code 2111112. (Standard)
- "v2830sb_b1_3882" is used for modem code 2111302 (recommended for Czech)
- "v2830sb_b2_3882" is used for modem code 2121302.(recommended for Slovakia)
- "v2830sb_b4_3882" is used for modem code 214702.
- "v2830sb_b5_3882" is used for modem code 2111312.
- "v2830sb_b6_3882" is used for modem code 215202.
- "v2830sb_b7_3882" is used for modem code 246302.