

Release Note for Vigor2920 Series

Firmware Version: 3.3.7.1
Built Date: March, 02, 2012
Applied Models:
Vigor2920/Vigor2920n/2920Vn

Vigor2920 series, a firewall broadband router with dual-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet. The gigabit 2nd WAN and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- Support USB LTE modem. Please visit DrayTek web side for getting the detailed information for LTE models.
- Support customized message for login page.

Improvement

- Corrected: Syslog file cannot be deleted if it is created before the router reboots.
- Corrected: SMS message may not be sent out.
- Corrected: Bandwidth Limit setting can not be applied to LAN2/3/4.
- Corrected: Clients can not access FTP (Internet server) by active/passive mode.
- Corrected: New wireless client cannot connect to the router after the WLAN connection is forced down on schedule.
- Corrected: PC cannot visit websites through the router after clearing a running URL filter profile.

Related Information

- Get the document, please visit
<http://www.draytek.com/user/PdInfoDetail.php?Id=117>
- Get the new firmware, please visit
<http://www.draytek.com/user/SupportDownloads.php>

- Get the customer service support, please visit
<http://www.draytek.com/user/ContactHeadquarters.php#Headquarters>
- Get the regulatory compliance information
<http://www.draytek.com/user/AboutRegulatory.php>
- Get information for global partners
<http://www.draytek.com/user/Globalpartners.php>

Known Issue

- None

Notes

Modifications

- None