

## Release Note for Vigor2960

**Firmware Version: 1.0.8.2**  
**Release Date: June 23, 2014**  
**Applied Models:**  
**Vigor2960**

---

Vigor2960, a firewall broadband router with dual-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet FTTx. The dual-WAN and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

### New Features

- None.

### Improvement

- Improved: Upgrade OpenSSL to 0.9.8za for some security issues.
- Fixed: WCF (Web Content Filter) cannot be enabled when myVigor Portal changes Service Name from Commtouch to Cyren.
- Fixed: Some bugs about HA (High Availability).
- Fixed: DDNS failover 3G WAN didn't work.
- Fixed: Daylight Saving didn't work for UTC+1(Ljubljana).

### Known Issue

- VPN Trunk tunnel doesn't work well when the profile name is more than 15 characters.
- You need to disable "Force IPsec with L2TP" options for pure L2TP tunnel in **VPN and Remote Access >> PPP General Setup**.

# Notes

## *Modifications*

- None