

Release Note for Vigor2960

Firmware Version: 1.0.9.1
Release Date: February 03, 2015
Applied Models:
Vigor2960, Vigor2960F

Vigor2960, a firewall broadband router with dual-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet FTTx. The dual-WAN and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.9 or later.

New Features

- None.

Improvement

- Improved: IGMP Proxy supports to send out packet without PPPoE header in PPPoE mode.
- Improved: Support Bandluxe C330 USB 3G modem.
- Improved: Change SSL VPN tunnel MTU according to WAN MTU.
- Corrected: PPTP remote dial-in user cannot access Internet.
- Corrected: PPPoE WAN IOP issue with some ISP
- Corrected: Policy Route cannot work for return path.
- Corrected: The IPSec option, **Auto Dial Out if WAN1 Down**, still works when it is disabled.
- Corrected: Memory is high when Data Flow Monitor is enabled.
- Corrected: Access Control List cannot work correctly.
- Corrected: GHOST (CVE-2015-0235) vulnerability in Glibc.

Known Issue

- You need to disable "Force IPsec with L2TP" options for pure L2TP tunnel in **VPN and Remote Access >> PPP General Setup**.

Notes

Modifications

- None