

Release Note for Vigor3910 Series

Firmware Version:	3.9.1.3
Release Type:	Normal
Applied Models:	Vigor3910

New Features

- None.

Improvement

- Improved: Make specific software adjustment for the newer version hardware GPY211 and GSW140.
- Improved: Improvement for the WAN up / down mechanism by ignoring the erroneous port status update.
- Improved: Make sure the acceleration mechanism is aware of interface status (i.e. flush related conntrack when an interface is down).
- Corrected: The issue of auto reset to factory default if the configuration was corrupted.
- Corrected: The issue that dial-in IPsec Aggressive VPN connection could not be up again after a reboot.
- Corrected: The issue that SSL VPN LAN-LAN did not forward packets with MTU 1395~1400.
- Corrected: The issue of MSS (maximum segment size) in SSL VPN.

Known Issue

- None.

Note

The following items will be ready in the future release:

- USB Applications
- Central Management
- WAN >> Multi-VLAN >> Port-based bridge
- Bandwidth Management >> APP QoS / VoIP QoS

The following traffic will be accelerated (in the fast path) in the future release

- All IPv6 traffic
- Non-IPsec VPN traffic (e.g. PPTP, SSL)
- VigorACS server will be fully compatible with this router