

## Release Note for VigorAP 1060C

|                   |               |
|-------------------|---------------|
| Firmware Version: | 1.4.6         |
| Release Type:     | Normal        |
| Applied Models:   | VigorAP 1060C |

VigorAP 1060C is a ceiling mount Access Point with PoE for offering power supply and support 1.2Gbps @2.4GHz, and 2.4Gbps @5GHz (11ax).

### New Features

- None.

### Improvement

- Improved: Improve the OpenSSL security (CVE-2022-0778).
- Improved: Support "AutoSelect" for 2.4GHz as the default setting.
- Improved: Add the TR-069 default settings for the French country code.
- Improved: Support Band1 to Band4 for 5GHz WiFi channel (for Hong Kong).
- Improved: Add a note regarding importing the MAC Address device object list from CSV.
- Corrected: An issue of failure to verify AuthKey in connecting Vigor AP.
- Corrected: An issue with the Range Extender mode not working after the AP was restarted.
- Corrected: An issue of clients communicating with each other with the same radio but different SSIDs.
- Corrected: An issue of wireless connection rate error for the channel 11b+11g+11n+11ax for 2.4GHz mode.
- Corrected: An issue of APM failure on the Vigor router when upgrading the firmware of VigorAP from 1.4.3 to 1.4.4.

### Known Issue

- None

### Notes

- None.