

Release Note for VigorAP 903

Firmware Version:	1.4.8
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	VigorAP 903

VigorAP 903 is 11ac Wave 2 dual-band wireless mesh access point with a 5-port LAN switch, which port A1 supports 802.3at PoE-In. It provides the flexibility and advanced features for professional users to take full management of the wireless network, including the mesh technology, which aims for providing an easy way to expand the wireless network in minutes.

New Features

- None.

Improvement

- Improved: Improve the web GUI security (CVE-2019-16645).
- Corrected: An issue with the 802.11r roaming stopped working after the system reboot.

Known Issue

- Web access via HTTPS doesn't work well after the firmware upgrade. It is recommended to use HTTP instead or use either of the methods below to fix this problem temporarily.
 - (a) Enable "Enforce HTTPS Access" on web System Maintenance >> Management.
 - (b) Use "https://{IP}/login.asp" to access web. (Add "/login.asp" manually after IP. For example: "https://192.168.1.11/login.asp")

Notes

- None.