

Release Note for VigorIPPBX 3510 Series

Firmware Version: 3.5.7.4
Release Date: April 1, 2013
Applied Models: VigorIPPBX™

The VigorIPPBX 3510 is a dual-WAN broadband router with IP PBX function. The 2nd WAN interface is shared with the 4th LAN port. These two WANs can connect to DSL/Cable modem or fiber media converter for policy-based load-balance, fail-over and BoD (Bandwidth on Demand); it also features advanced bandwidth control mechanism such as IP-layer QoS, NAT Session Limitation, Bandwidth Borrowed, etc., to allow easy, flexible, reliable access control and bandwidth management.

New Features

- Support VPN trunk function.

Improvement

- Corrected: Can't accept 2nd IP by using VoIP module IP address.
- Corrected: WUI setting error when SIP alias profile name is configured with 11 characters.
- Corrected: Can't dial trunk number via FXS.
- Corrected: Modification on setting up IPPBX functions by IPPBX Wizard.
- Corrected: IOP issue with Vega FXO VoIP gateway when IPPBX acts as a custom trunk.
- Corrected: Modification on setting hunt group.
- Improved: Support TR-069 via customized WAN interface.

Known Issue

- SIP trunk and extension configuration backup are not compatible with IE6.0. Please use Firefox to test the feature.
- If ISDN trunk has existed incoming call and outgoing call at the same time, out-going call would not be disconnected when time budget exceeded until incoming call disconnected.

Notes

- Please use the firmware upgrade utility to backup/restore *V3510_xxx.cfg* and *VoipModule config*.
- As for the relation between VigorIPPBX router and System Prompt file, refer to **FAQ:** ***Please upload the newest System Prompt after upgrading Vigor IPPBX firmware V3.5.6*** for detailed information.
- To send a fax via IPPBX virtual fax function, you need to use Virtual FAX Utility.