

Release Note for VigorSwitch P2260

Firmware Version: 2.67
Built Date: March 18, 2010
Applied Models:
VigorSwitch P2260

New Features

- None

Improvement

- Change the file name of fake-server.html into invalid_server.html.
- Modify the GVRP Configuration page.
- Corrected: Cold Start/Warm Start Trap will not be sent out.
- Corrected: Can not receive Warm/Cold Start Trap value.
- Corrected: SFP icon will be shown on the screen when there is no SFP inserted.
- Corrected: Micronet CM SFP icon is not the same as other CM SFP icon.
- Corrected: If there are two or more devices configured as Master devices, the one with the minimum MAC values could not be specified as the Master finally.
- Corrected: Error display of DNS value.
- Corrected: A bar appears on the WUI while being browsed by using Firefox.

Known Issue

- None

Notes

Modifications

- None

