

Release Note for Vigor2760 Series (Delight)

Firmware Version:	3.8.8.2
Release Type:	Critical
Applied Models:	Vigor2760, Vigor2760n, Vigor2760Vn

DrayTek launches Vigor2760 series – high speed router, perfectly complied with VDSL2/ADSL2/ADSL2+ environment including Vigor2760, Vigor2760n and Vigor2760Vn for speed-wanted customers. For more details of the product information, please visit our website on <http://www.draytek.com>.

This is a critical update - You should upgrade such Vigor router immediately with firmware containing these improvements.

File and Modem Code

Note: For DSL models, there will be two folders: STD and VECTOR. The files in VECTOR folder implement a new DSL driver, which supports G.Vectoring on VDSL. If you're using a VDSL line, VECTOR firmware may brings out better performance; however, please consult your ISP to check if G.Vectoring is required. We also provide several versions of Vector firmware to avoid the interoperability issue. You could just try the other one if the one you use cannot synchronize or get the speed that you expected.

Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,

- "Vigor2760_v3.8.8.2_STD.zip" is used for modem code 548006_544401 & 560816_552011.
- "Vigor2760_v3.8.8.2_VECTOR1.zip" is used for modem code 567517_562301 & 566f07_562701.
- "Vigor2760_v3.8.8.2_VECTOR2.zip" is used for modem code 574307_571801 & 573807_571701.
- "Vigor2760_v3.8.8.2_VECTOR3.zip" is used for modem code 576d17_572801 & 574307_571801.
- "Vigor2760_v3.8.8.2_VECTOR4.zip" is used for modem code 579F17_573F01 & 573807_571701.

For Annex B Model,

- "Vigor2760_v3.8.8.2_STD.zip" is used for modem code 548006_544512 & 551716_553312.

- "Vigor2760_v3.8.8.2_VECTOR1.zip" is used for modem code 565607_567002 & 565606_567002.
- "Vigor2760_v3.8.8.2_VECTOR2.zip" is used for modem code 573307_571c02 & 565607_567002.
- "Vigor2760_v3.8.8.2_VECTOR3.zip" is used for modem code 573307_571c02 & 565607_567002.
- "Vigor2760_v3.8.8.2_VECTOR4.zip" is used for modem code 573307_571c02 & 565607_567002.

New Features

- None.

Improvement

- This firmware includes improvements to harden the web interface against attacks. We have become aware of specific attacks against router, including DrayTek models where hackers have altered specific settings relating to your DNS servers and DHCP settings. You should urgently check those settings on your router. If they appear to have been tampered with, correct them and change your admin password and for any other config anomalies. Restore a config backup if you have one (from prior to the attack). We continue to investigate this issue but the first priority was to issue updated firmware.

Known Issue

- None.