

Release Note for Vigor2920 Series

Firmware Version: 3.6.8

Release Date: January 29, 2015

Applied Models:

**Vigor2920/Vigor2920n/2920Vn/Vigor2920F/Vigor2920Fn/Vigor2920FV/
Vigor2920FVn**

Vigor2920 series, a firewall broadband router with dual-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet. The gigabit 2nd WAN and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- None

Improvement

- Improved: SSL3 now disabled in favour of TLS by default for SSL tunnels and web management.
- Improved: Allow to get/set SNMP by TR-069.
- Improved: Support RFC3021 (Using 31-Bit Prefixes on IPv4 Point-to-Point Links).
- Improved: Support parameter for LAN port control.
- Improved: Support Ethernet LAN port administratively down feature.
- Improved: Improve the mechanism of TCP SYN to prevent from being unable to access into web user interface due to abnormal TCP connection in Portugal area.
- Corrected: 3G backup mode can't work after 36 days.
- Corrected: Registration failed for SIP phone in LAN.
- Corrected: Firewall blocks IPv6 incoming routing traffic issue.

Known Issue

- None

Notes

Modifications

- None