

## Release Note for Vigor2952 Series

Firmware Version:	3.9.4.1
Release Type:	Normal
Applied Models:	Vigor2952, Vigor2952P, Vigor2952n, Vigor2952Pn

Vigor2952 is a broadband router with dual-WAN interface. It provides policy-based load-balance, fail-over and BoD (Bandwidth on Demand), also it integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

### New Features

- None.

### Improvement

- Improved: Adjust router's self-signed certificate to comply with new browser restrictions. Start on 2020-09-01, many client OSes/browsers will enforce publicly trusted TLS server certificate lifetime to 398 days or less, and connections will be rejected if the certificates violated this rule, so this firmware patch will automatically re-sign all the self-signed certificates lifetime to 395 days (was 2 years or longer in older versions).
- Corrected: An issue of SIP port 5060 not working.

### Known Issue

- None.

### Note

- None.