

Release Note for Vigor2960

Firmware Version:	1.5.1
Release Type:	Critical
Applied Models:	Vigor2960 Series

This is a critical update - You should upgrade such Vigor router immediately with firmware containing these improvements.

New Features

- None.

Improvement

- Improved: Improved the WebGUI security.
- Corrected: The issue of changing LDAP server port on WUI.
- Corrected: The issue of port number configuration for Two-FA authentication.

Known Issue

- None.

Note

- Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.9 or later.