

Release Note for Vigor3900 Series

Firmware Version:	1.3.3
Release Type:	Normal
Applied Models:	Vigor3900

Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.8.x and later.

New Features

- None.

Improvement

- Improved: Improvement related to firmware security.

Known Issue

- None.