

Release Note for VigorAP 912C

Firmware Version:	1.3.5
Release Type:	Normal
Applied Models:	VigorAP 912C

VigorAP 912C is a ceiling-mount Wi-Fi for business networks. It has a capacity of up to 256 concurrent active users, ideal for a high-density environment such as a BYOD workplace. The low-profile appearance and PoE power supply provide the flexibility in deployment.

New Features

- Support TLS 1.3.

Improvement

- Improved: Improve the compatibility and stability for Mesh network.
- Improved: Improve the vendor display status on MDM>>Station Nearby.
- Improved: Support Preferred Uplink for mesh node (Mesh>>Mesh Setup).
- Improved: Improve the WiFi security (CVE-2019-15126 and CVE-2020-3702).
- Improved: Add notes related to SSID on Wireless LAN(5GHz)>>General Setup.
- Improved: Add a warning message related to Wireless Downlink Band for wireless LAN 5GHz.
- Improved: Add an option to disable/enable TLSv1.3 on System Maintenance >> Management.
- Improved: Support to enable / disable the Reset button on System Maintenance >> Management.
- Improved: Text modification on Mesh >> Basic Configuration Sync / Advanced Configuration Sync.
- Improved: Modify the name and order of the wireless security options (Wireless LAN>>Security Settings).
- Corrected: An issue that the Range Extender mode does not work for WIFI clients.
- Corrected: An issue of display error on web Quick Start Wizard >> Operation Mode.
- Corrected: An issue of failing to connect VigorAP mesh root and node.

- Corrected: An issue of channel display error on Configuration >> Wireless LAN >> General Setup.

Known Issue

- None.