

Release Note for VigorSwitch G2240

Firmware Version: 1.42

Date: April, 19, 2011

**Applied Models:
VigorSwitch G2240**

New Features

- None

Improvement

- Improved: While forwarding data, pulling out /replacing job would cause looping at fiber port.
- Improved: Port description is not written in flash.
- Improved: Configuration file import would cause device crash .

Known Issue

- None

Notes

Modifications

- None